



TNO Quality Services BV  
Enschede

Return address: P.O. box 337, 7500 AH Enschede, The Netherlands

Unifloor B.V.  
Att. Mr. G. van den Brand  
Munsterstraat 24  
7418 EV DEVENTER  
The Netherlands

Postal address:  
P.O. Box 337  
7500 AH Enschede  
The Netherlands

Parking and delivery:  
Josink Esweg 10  
7545 PN Enschede  
The Netherlands

[www.tno-quality.com](http://www.tno-quality.com)

T +31-88-8887888  
F +31-88-8887859

[Jan.brinks@nl.tuv.com](mailto:Jan.brinks@nl.tuv.com)

**Report number T09.25024.02**

**Sponsor:**

Contractor, manufacturer : Unifloor Underlay Systems B.V.  
Product name/family : Product Family 2, see appendix I, page five.

**Date**  
17 February 2010

**Project number**  
T09.25024

**Purpose :**

Classification accordance EN 13501:2007.

**Telefoon cliënt**  
+31 570-855533

Reaction to fire test, according to:

- EN ISO 11925-2:2002 Reaction to fire tests for building products, Part 2:  
Ignitability when subjected to direct impingement of flame (ISO 11925-2:2002).
- EN ISO 9239 reaction to fire tests for floor coverings, Part 1: Determination of the  
burning behaviour using a radiant heat source (ISO 9239-1:2002).

**Fax cliënt**  
+31 570-855544

**Article**  
Product Family 02

**Results:**

On pages two up to and including four.

**Appendices**  
1, page 5

TQS applies the Standard Conditions for  
research instructions given to TNO. The  
Standard Conditions will be sent on request



**Date**  
17 February 2010

**Project number**  
T09.25024

**Article**  
Product Family 02

**Page**  
2 of 5

**Test results: EN-ISO 11925-2:2002 Small burner examination**

Date of test : October-November 2009  
Conditioning time, climate : min. 3 days,  $23 \pm 2$  °C and  $50 \pm 5$  %  
Description of substrate : 6 mm. Fibre cement board,  $1800 \text{ kg/m}^3$ .  
Flame application : Surface.  
Application time : 15 seconds.

**Assessment:**

**FAMILY 2** underlay flooring, did not fulfill the requirements EN ISO 11925-2<sup>1</sup> (Fs  $\leq$  150 mm within 20 s.).

Based on the test results and evaluating the criteria for classification according to clause 8 of the EN-ISO 11925-2:2002 the examined **FAMILY 2** underlay flooring proved to be incapable of resisting, for a short period, a small flame attack without substantial flame spread.

If assessed according to Table 1 of the European classification standard EN 13501-1:2002 "**Classification standard for building product and building elements**" the examined product will be classified as follows: **Class F<sub>n</sub>**.

---

<sup>1</sup> Under conditions of surface flame attack and, if appropriate to the end-use application of the product, edge flame attack.



**Date**  
17 February 2010

**Project number**  
T09.25024

**Article**  
Product Family 02

**Page**  
3 of 5

**Test results: EN ISO 9239-1:2002. Radiant Panel test.**

Date of testing : October – November 2009  
Conditioning time, climate : min. 3 days,  $23 \pm 2$  °C and  $50 \pm 5$  %  
Description of substrate : 6 mm. Fibre cement board,  $1800 \text{ kg/m}^3$ .  
Sampling procedure : by contractor.  
Description of cleaning used : none  
Fixing method : loose laid

Quality	Test specimen, orientation	CRF ( $\text{kW/m}^2$ )	Smoke production (%.min)
Marathon Super	longitude	2.02	88
Marathon Dual	longitude	2.90	35
Redupax +	longitude	1.54	45

Table 1: A list of radiant panel test results (EN-ISO 9239-1) from qualities of the Family of Products 2.

Remarks: no flashing, transitory- or sustained flaming,  
\* specimen extinguished naturally

**Classification criteria Class F<sub>FL</sub>:**

- No performance



**Date**  
17 February 2010

**Project number**  
T09.25024

**Article**  
Product Family 02

**Page**  
4 of 5

**Conclusion:**

According to EN 13501:2007 the tested samples of the aforementioned **Family 2** meets the requirements of **Class F<sub>FL</sub>**.

**Statements:**

The test results only relate to the behaviour of the test specimens of the examined product under the particular conditions of the test in laboratory conditions; they are not intended to be the sole criterion for assessing the potential fire hazard of the product in use. The method might not be suitable if the product is exposed to much larger flames or heat radiant sources.


The validity of this report will expire five years after its issue or directly after alterations or modifications of the examined product(combination)(s) and/or the criteria. This report shall not be reproduced, except in full, without the written approval of the testing laboratory.

Project leader:

Mr. J. Brinks

Author:

Mrs. I. Pierik



b.a.

All rights reserved.

No part of this report may be reproduced, provided to and/or examined by third parties, and/or published by print, photoprint, microfilm, in electronic form or any other means without the explicit previous written consent of TNO (Quality).

In case this report was drafted within the context of an assignment to TNO (Quality), the rights and obligations of contracting parties are subject to the General Terms & Conditions for Advisory, Research and Certification assignments to TNO (Quality) and/or the relevant agreement concluded between the contracting parties. © 2009 TNO



**Date**  
17 February 2010

**Project number**  
T09.25024

**Article**  
Product Family 02

**Page**  
5 of 5

## APPENDIX I: PRODUCT FAMILY 2, description of samples

### Description of sample:

Type of surface : underlayment/underflooring

Quality	Total mass	Total thickness
	kg/m <sup>2</sup>	mm
Marathon Super	3.1	6
Marathon Dual	3.1	6
Redupax +	2.7	8